

**APPENDIX B**

**SITE PHOTOGRAPHS: WILLISTON WASTE DISPOSAL FACILITY**

Picture	Description
	<p>North view</p> <p>Taken on 11 September 2015</p>
	<p>Poor trenching, waste burning, view east.</p> <p>Taken on 11 September 2015</p>
	<p>Trenches for abattoir waste.</p> <p>Taken on 11 September 2015</p>





More trenches for abattoir waste.

Taken on 11 September 2015



View south to the Sac River.

Taken on 11 September 2015



Porcupine quill.

Taken on 11 September 2015