

TAUNG PICNIC AREA ABLUTION BLOCK PROPOSAL

REPAIR AND RENOVATION OF TAUNG ABLUTION BLOCK IN THE PICNIC AREA




Fig 12: intervention phasing




Fig 13: existing abluition block



Fig 14: 3d visualization after repairs and renovations

TUMENG WATERFALLS: ABLUTION BLOCK PROPOSAL







Fig 15: 3d visualization of the Tumeng ablution and guardhouse block