

THT370579122 - TE Mrs TSHILISANANI INNOCENT MUZILA

Site Pictures

*Figure 1 The existing line with the T-off position down the road.*



Figure 2 The T-off Pole. The line runs to the left of the small dirt road shown in the picture.







Figure 3 One of the pegs on site



*Figure 4 The line continues to run to the left of the dirt road*



*Figure 5 The line crosses from the right(previous left) to the corner of the fence shown in the picture below*







*Figure 6 The power line crosses the small dirt road to supply the customer's yard*

