



APPENDIX B

SITE PHOTOGRAPHS: VIOOLSDRIFT LANDFILL SITE

Photograph	Description
<p data-bbox="188 376 209 405">1</p> 	<p data-bbox="1241 376 1476 472">Vantage point: Perimeter facing north west.</p> <p data-bbox="1241 517 1476 613">Disposal and burning of general waste.</p> <p data-bbox="1241 696 1436 763">Photo taken 02 March 2016.</p>
<p data-bbox="188 1052 209 1081">2</p> 	<p data-bbox="1241 1052 1452 1149">Vantage point: Perimeter facing south.</p> <p data-bbox="1241 1193 1396 1223">Vacant land.</p> <p data-bbox="1241 1305 1436 1373">Photo taken 02 March 2016.</p>

3



Vantage point:
Perimeter facing
south east.

Disposal of
general waste.

Photo taken 02
March 2016.

4



Vantage point:
Perimeter facing
north.

Disposal of
general waste on
either side of the
dirt road/ track.

Photo taken 02
March 2016.

5



Vantage point:
Perimeter facing east.

Disposal and
burning of general
waste.

Photo taken 02
March 2016.

6



Vantage point:
Perimeter facing west.

Disposal of
general waste,
including building
waste (rubble).

Photo taken 02
March 2016.

7



Vantage point:
Perimeter facing
south west.

Disposal of
general waste.

Photo taken 02
March 2016.

8



Vantage point:
Perimeter facing
north east.

Illegal dumping
and burning of
waste on either
side of the dirt
road/ track.

Photo taken 02
March 2016.