



View to the north of the site (Delmore Park ext. 2)



View to the north-east of site (part of Delmore park ext. 2)



View to the north-west of the site, possible entrance to site, cnr Lower Boksburg Rd (Commissioner St) and Du Preez St.)



View to the south-west, power lines visible



View to the south-east of the site, vegetation present on land, indication of disturbed land



View to the south-west, same vegetation present, disturbed land



View to the south-east, visible road/track markings, disturbed land, man-made dam visible in the distance



View to the south-west, visible road/track markings, disturbed land, and power lines visible in the distance



View to the south of the site, power lines visible, evidence of disturbed land



View to the south-east, man-made dam visible, between the site and the dam is a wetland



View to the south-west, power lines, disturbed land (constant/same vegetation)



View to the north-east of the site, Delmore Park ext. 2



View from the south-west corner of the site, looking towards the north-east/east



View from the south-west corner. Alongside Lower Boksburg Rd (Commissioner St), main road



View from the south-west corner of the site, looking onto the Lower Boksburg Rd (Commissioner St), main road



Image 17



Image 18



View to the north-east from the south/south-west, Delmore Park ext2. Evident land disturbance



Power lines, outside of site boundary.