



Image of existing over which the upgrade and construction will be implemented, seen from eastern approach.



View river on upstream side.



View of river at downstream side. Note dumping and weeds on the bank.



Image of weeds and scour at the immediate upstream bank.



Image of riparian area to be affected by the bridge. Note weed encroachment.



Grimthorpe avenue gravel section to be upgraded.



Upgrade of road from Rodger avenue avenue/grimthorpe avenue intersection.



Image of vegetation along grimthorpe avenue, comprising mainly alien species.



Image of vegetation along grimthorpe avenue.



Image of Grimthorpe, eastern approach to be upgraded.



Image of sewage treatment works near western approach.



View of encroached open space/riparian area.



Immediate upstream side of existing bridge, note weeds, dumping, and cyperus.



Downstream side of existing bridge.