



PHOTOGRAPH 19 -----VIEW OF LIGHT FITTING - HOUSING TO ELECTRICAL CONNECTION IS ALSO RUSTING AWAY - FITTING IS LYING LOOSE WITH SUB STANDARD CONNECTION (DANGEROUS)



PHOTOGRAPH 20 -----VIEW OF LIGHT FITTING - HOUSING TO ELECTRICAL CONNECTION IS ALSO RUSTING AWAY - FITTING IS LYING LOOSE WITH SUB STANDARD CONNECTION (DANGEROUS)

SIGNATURE
architectural studio

UNIT 24 CANFORD PARK, 53 ANTHONY ROAD, DURBAN NORTH, 4051
TELEPHONE : 0826644644

91 BEREA PARK