



PHOTOGRAPH 29 ---- LACK OF MAINTENANCE IS EVIDENT IN THIS PHOTO



PHOTOGRAPH 30 ---- BORER INFESTED WINDOW IS SUPPORTED BY ONE HINGE

**SIGNATURE**  
architectural studio

UNIT 24 CANFORD PARK, 53 ANTHONY ROAD, DURBAN NORTH, 4051  
TELEPHONE : 0826644644

91 BEREAS PARK