



PHOTOGRAPH 17 ---- VIEW OF CARPORT - THIS STRUCTURE IS ABOUT TO COLLAPSE
ROOF SHEETING HAS ALMOST RUSTED AWAY



PHOTOGRAPH 18 ---- VIEW OF CARPORT - THIS STRUCTURE IS ABOUT TO COLLAPSE
ROOF SHEETING HAS ALMOST RUSTED AWAY

SIGNATURE
architectural studio

UNIT 24 CANFORD PARK, 53 ANTHONY ROAD, DURBAN NORTH, 4051
TELEPHONE : 0826644644

91 BEREA PARK