

SITE PHOTOGRAPHS



Photo Plate 1: Sign of the Driel Dam



Photo Plate 2: Access to the Driel Dam



Photo Plate 3: Vegetation around Driel Dam



Photo Plate 4: Access control at Driel Dam



Photo Plate 5: The section which requires rehabilitation after erosion



Photo Plate 6: A view of the Dam wall



Photo Plate 7: The section which requires rehabilitation after erosion



Photo Plate 8: The section which requires rehabilitation after erosion



Photo Plate 9: Material to be used for rehabilitation.