

KEY SITE IMAGES



Image of road and surroundings



Note grassland and sylviculture plantations



Road to be upgraded, note lack of sensitive features on either side



Road to be upgraded, note lack of sensitive features on either side



Road to be upgraded, note silviculture, disturbed grassland and relic wetland



Road to be upgraded



Road to be upgraded, note drainage line



Note wetland and housing



These trees will be removed to accommodate the upgrade



Image of plantations and wet areas



Road to be upgrade

