



AMAFA / HERITAGE KWAZULU-NATAL SURVEYING FORM

| | | | | | | | | | | | |
|--|--|--|--|---------------------------------|--|---|--|--|--|----------------------|--|
| SURVEY OF: KwaSani Local Municipality | | | | DATE RECORDED: October 2013 | | | | | | | |
| PROPERTY NAME: STREET ADDRESS: 11 Arbuckle Road, Himeville | | | | | | | | | | | |
| GPS. CO-ORDINATES | | 29.75439 ° | | S | | 029.50991° | | | | | |
|  | |  | | ERF NUMBER / FARM NUMBER: 33 | | | | | | | |
| | | | | ZONING | | | | | | | |
| | | ARCHITECT / BUILDER Unknown | | CONSTRUCTION DATE Unknown | | BUILDING STYLE Edwardian | | BUILDING TYPE Veranda House | | | |
| | |  | | PRESENT USE Residential | | OCCUPIED (yes / no) Yes | | CONDITION (good / fair / poor / derelict) Good | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| DESCRIPTION: Single storey house. Corrugated iron, hipped roof. Mudbrick walls, plastered and painted. Timber-frame sash windows. Timber doors with glass casements. Cornered veranda with timber posts and a small wall around it. Brick chimneys. CONSTRUCTION: Mudbrick and corrugated iron. ALTERATIONS (with dates): Half enclosed veranda with arched, steel-frame, side-sash window. House extended in the back with raised platform. Timber lean-to to the side of the house. SITE FEATURES: Pebble entrance way with plants surrounding. Plants covering front fence. HISTORY: Unknown SOURCES / REFERENCES: EVALUATION :(cross where relevant) | | | | | | | | | | | |
| Outstanding importance | | Significant | | Contributing | | X Irrelevant | | Intrusive | | Vacant / undeveloped | |
| SIGNIFICANCE (cross where relevant) | | | | | | | | | | | |
| ARCHITECTURAL / AESTHETIC | | | | HISTORICAL | | | | | | | |
| Important example of a building type | | | | X | | Associated with historic person or group | | | | | |
| Important example of a style or period in history | | | | X | | Associated with historic event or activity | | | | | |
| Fine details, workmanship or aesthetics | | | | | | | | CULTURAL / POLITICAL / SOCIAL / EDUCATIONAL / RELIGIOUS / ECONOMIC | | | |
| Work of a major architect or builder | | | | | | | | Associated with any of the above | | | |
| ENVIRONMENTAL | | | | | | | | Illustrative of an historical period | | | |
| Landmark in village, town or city | | | | | | | | SCIENTIFIC / TECHNICAL | | | |
| Contributes to character of street or square | | | | X | | Example of industrial, technical or engineering development | | | | | |
| Contributes to character of a neighbourhood or area | | | | | | | | Important to archaeology, palaeontology, geology or biology | | | |
| Part of an important group of buildings | | | | | | | | New, rare or experimental building techniques | | | |
| MOTIVATION AND STATEMENT OF SIGNIFICANCE: The building is older than 60 years, but is heavily altered. | | | | | | | | | | | |
| RECORDED BY: Nadine Franzsen & Shadrack Maluleke | | | | CONTACT NUMBERS: 033-394-0739 | | | | | | | |

03/10/2013