



AMAFA / HERITAGE KWAZULU-NATAL SURVEYING FORM

| | | | | | | | |
|--------------------------------------------------------------------------------------------------------|--|-------------|--|--------------------------------------------------------------------|--|--------------------------|--|
| SURVEY OF: KwaSani Local Municipality | | | | DATE RECORDED: September 2013 | | | |
| PROPERTY NAME: Waterford | | | | | | | |
| STREET ADDRESS: Waterford on R617, Underberg | | | | | | | |
| GPS. CO-ORDINATES | | 29.85333° | | S | | 029.32480° | |
| | | | | | | E | |
| | | | | | | ERF NUMBER / FARM NUMBER | |
| | | | | | | ZONING | |
| | | | | ARCHITECT / BUILDER Unknown | | | |
| | | | | CONSTRUCTION DATE Unknown | | | |
| | | | | BUILDING STYLE | | | |
| | | | | BUILDING TYPE | | | |
| | | | | PRESENT USE | | | |
| OCCUPIED (yes / no) | | | | | | | |
| CONDITION (good / fair / poor / derelict) Fair | | | | | | | |
| DESCRIPTION: Face-brick walls with corrugated iron gable roof, timber side sash windows and door frame | | | | | | | |
| CONSTRUCTION: Face-brick walls, corrugated iron roof, timber door and window frames | | | | | | | |
| ALTERATIONS (with dates): Ivy plants creeping on the wall | | | | | | | |
| SITE FEATURES: Well maintained grass yard with swimming pool at the back | | | | | | | |
| HISTORY: The current owners have been there for 16 years | | | | | | | |
| SOURCES / REFERENCES: | | | | | | | |
| EVALUATION :(cross where relevant) | | | | | | | |
| Outstanding importance | | Significant | | Contributing | | Irrelevant X Intrusive | |
| | | | | | | Vacant / undeveloped | |
| SIGNIFICANCE (cross where relevant) | | | | | | | |
| ARCHITECTURAL / AESTHETIC | | | | HISTORICAL | | | |
| Important example of a building type | | | | Associated with historic person or group | | | |
| Important example of a style or period in history | | | | Associated with historic event or activity | | | |
| Fine details, workmanship or aesthetics | | | | CULTURAL / POLITICAL / SOCIAL / EDUCATIONAL / RELIGIOUS / ECONOMIC | | | |
| Work of a major architect or builder | | | | Associated with any of the above | | | |
| ENVIRONMENTAL | | | | Illustrative of an historical period | | | |
| Landmark in village, town or city | | | | SCIENTIFIC / TECHNICAL | | | |
| Contributes to character of street or square | | | | Example of industrial, technical or engineering development | | | |
| Contributes to character of a neighbourhood or area | | | | Important to archaeology, palaeontology, geology or biology | | | |
| Part of an important group of buildings | | | | New, rare or experimental building techniques | | | |
| MOTIVATION AND STATEMENT OF SIGNIFICANCE | | | | | | | |
| RECORDED BY: Nadine Franzsen & Shadrack Maluleke | | | | CONTACT NUMBERS: 033-394-0739 | | | |